

COURSE INFORMATION

Course Number: FWL 1210

Course Name: Fabrication Equipment Technology

CREDIT-BY-ASSESSMENT (CBA) COMPETENCY LIST READING A TAPE MEASURE

• Recall how to properly label, record, locate, and recognize all increments of measurement as well as demonstrate proper use of a tape measure.

DIMENSIONS

 Illustrate proper knowledge of linear, angular, reference, baseline, and broken chain dimensioning. This will include identification of dimensioning holes and slots as well as tolerances.

HOW TO READ WELDING SYMBOLS

• Define how to properly read, as well as use the welding symbols of reference line, arrow side information, other side information, tail, finish symbol, special information, and reference.

MANUFACTURE PARTS BASED OFF BLUEPRINTS

 Demonstrate how to properly manufacture parts based off of their translation of a blueprint.

DESIGN AND DIMENSION ORTHOGRAPHIC DRAWINGS FOR DIFFERENT VIEWS OF A PART USING AUTO-CAD SOFTWARE

• Given a print to work from, construct and dimension a drawing using orthographic projection in AutoCAD.